FOR

COMERCO INC. OLYMPIC STAIN DIVISION

BATAVIA, ILLINOIS

U.S. EPA ID: ILDO85224186

SS ID: NONE

TDD: F05-8711-048

PAN: FILO129SA

US EPA RECORDS CENTER REGION 5

**SEPTEMBER 15, 1988** 

Elements of this Screening Site Inspection Work Plan are considered confidential and pre-decisional in nature. Material and information contained within this report may not be released without the approval of the United States Environmental Protection Agency Region V Pre-Remedial Unit.



# ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415 International Specialists in the Environment recycled paper



# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5

# 230 SOUTH DEARBORN ST. CHICAGO, ILLINOIS 60604

REPLY TO THE ATTENTION OF: 5HR-11

Mr. Thomas Crause
Hazardous Substances Planning Unit
Illinois Environmental Protection Agency
2200 Churchill Road
Springfield, Illinois 62706

Dear Mr. Crause:

Site Name: COMERCO INC OLYMPIC STAIN DIV

Location: BATAVIA, 1L

Identification No: ILDOBS 224 186

Date: 9/15/88

Attached is a copy of the site inspection work plan which has been prepared for the site listed above. This document is considered to be <u>draft</u> and subject to changes and modifications based on actual conditions which may be encountered at the site.

Because this is considered to be a draft document, it should be for <u>official</u> use <u>only</u> and should not be distributed outside of your agency without prior <u>notification</u> and approval of the U.S. Environmental Protection Agency.

The document also contains a preliminary estimate of the Hazard Ranking System (HRS) score for the site and a projected score based on specific assumptions as addressed in the work plan. This information is considered predecisional. Therefore, it should not be released. Your field and district staff especially should be made aware of the predecisional nature of this score, the legal implications of releasing it relative to the National Priorities List (NPL) candidacy process, and therefore the need not to release any score. If you have any questions concerning release of this information, please contact Ms. Jeanne Griffin, of my staff, at (312) 886-3007.

If you have any comments on the work plan itself, please contact Mr. Charles Castle, of my staff, at (312) 886-5892, within eight calendar days. If we do not receive any comments written or verbal from you, then we will assume that the work plan is acceptable.

Please note that site inspections are carried out under CERCLA to determine if a site will make the NPL. Thus, extra sampling or other activities that serve only a State purpose should not be requested. We welcome suggestions based on the knowledge of you and your staff that will make for a better site inspection for NPL candidacy purposes.

Please talk with Mr. Castle as early within the eight-day period as possible in order that your suggestions can be evaluated and modifications made.

Sincerely yours,

Thomas F. Geishecker, Chief Program Support Section

Homas F. Herkbeller

Enclosure

Contents

**WORK PLAN** 

1

SITE MAPS

2

HRS WORKSHEETS 3

**APPENDIX** 

4

# WORK PLAN

#### SITE INSPECTION WORK PLAN

THIS DOCUMENT IS CONFIDENTIAL. Due to the predecisional nature of this document, this document and its attachments are not to be released vithout prior approval of the United States Environmental Protection Agency (U.S. EPA).

This site inspection work plan (VP) has been prepared by Ecology and Environment, Inc., or its subcontractor, C. C. Johnson and Halhotra, P.C., under the field investigation team (FIT) contract with U.S. EPA (No. 68-01-7347).

#### The objectives of this WP are to:

- o Prepare a preliminary Hazard Ranking System (HRS) score using HRS 1 (40 CFR 300, July 16, 1982) criteria based on existing file information (Part C of VP);
- Prepare projected HRS 1 scores based on experience and professional judgement (Part C of VP);
- o Provide ERS factor values using the revised ERS 2 (Federal Register proposed date, April 1988) criteria (Part D of VP);
- o Identify HRS 1 score data gaps (Part F of WP); and
- Propose site inspection activities to satisfy the HRS 1 score data gaps; technical approach and estimated LOB are provided (Parts P and J, respectively).

Unless otherwise stated, QA/QC protocol for site inspection activities are documented in the Quality Assurance Project Plan Region V FIT Conducted Site Inspections - Hay 1, 1987.

Note: This Work Plan has been prepared following the HRS model currently in use. Revisions will be made to bring the WP in agreement with the revised HRS requirements after promulgation in October 1988.

### A. GENERAL INFORMATION

CERCLIS SITE NAME: COMERCO INC. OLYMPIC STAIN DIVISION
ALSO KNOWN AS: OLYMPIC STAIN - CLOROX DIVISION
FORMERLY KNOWN AS: NONE
ADDRESS: 1020 OLYMPIC DR.
CITY: BATAVIA
STATE: TLLINOIS
COUNTY: KANE
2IP CODE: 60510 U.S. EPA ID: TL D085274186
SSID: None
TDD: F05-8711-048
PAN: FIL0129SA ·
FIT USE ONLY
VORK PLAN TYPE: SCREENING SITE INSPECTION (SSI) WORK PLAN
OTHER:
Ulispa.
*
,
PREPARED BY: BILL SCHAEFER (FIT) DATE: 7-21-88
<del></del>
APPROVED BY: M. Marty (FIT) DATE: 7-25-88  APPROVED BY: M. Marty (FIT) DATE: 9/15/88
Mary Marian
APPROVED BY: M. M. Antha (FIT) DATE: 9/15/88
H A HOL HAR ANT
U.S. EPA USE ONLY
PEUTEURN RY. /II C PDAN DATP.
REVIEWED BY: (U.S. EPA) DATE:
WORK PLAN APPROVED. Recommend issuance of TDD to implement the Work Plan
WORK PLAN APPROVED. No Further Remedial Action Planned (NFRAP).
FIARU REAL DE PARRE
WORK PLAN REJECTED.
COHKENTS:
COHHENTS:

### B. SITE INFORMATION

This section of the VP presents current and historic information pertaining to the site, including: site operations, storage/disposal methods, site property area, site status, owners and operators, permit information, and response/enforcement activities. A site location map is shown on Figure 1, located in Section 2.

		•
1. Site Operations (past	and present; o	check all that apply):
Above ground Belov ground Chemical manu Drum recycler Electroplater Foundry Incinerator Landfarm Landfill Midnight dump	storage facturer	Mining site  Open dump  Ore processor  Physical/chemical treament  Recycler/reclaimer  Surface impoundment  Underground injection  Vell field  Wood preserver  Other: Paint and stain  Production
References: 3	9	
2. Storage/Disposal Heth	ods (past and p	oresent; check all that apply):
		Vaste Quantity (amount/units of measure)
Drums, above Landfarm Landfill Open dump	ground	2540 drums (Est.)
Piles Surface impour Tank, above g Tank, below g	round	Unknown
References: 3	······································	•••••••••••••••••••••••••••••••••••••••
3. Site Property Area:		·
• • •	.84 (acre	es)

_		
References: 3		•
5. Owner/Operator History		
Current Ovner	Current Opera	tor
Name: Olympic Stain - Clorox Division Address: 1020 Olympic Dr.	Name: Same Address:	2
City, State, Zip Code: Batavia, Illinois 60510	City, State,	Zip Code:
Years of Ownership: 7 (1981-Present)	Type of Opera Years of Oper	tion: <u>Paint Manufacture</u>
Previous owners (list most recent first)	Previous oper (list m	ators ost recent first)
Name: Comerco Inc. Olympic Stain Div. Address: 1020 Olympic Dr.	Name: <u>Same</u> Address:	
City, State, Zip Code: Batavia, Illinois 60510	City, State,	Zip Code:
Years of Ownership: 4 (1977-1981)	Type of Opera Years of Oper	tion:ation:
Name:	Name:	
Address:	Address:	
City, State, Zip Code:	City, State,	Zip Code:
Years of Ownership:	Type of Opera	
i i	Years of Oper	ation:
References:		<u> </u>
6. Permit Information	Effective Date	Expiration Date
NPDBS to Fox River	10-14-77	10-31-82
AIR RCRA, PART A PART B		
SPCC PLAN STATE (specify):		
LOCAL (specify):		

.

7.	Response Activities (previous and coal) all that apply	
	Water supply closed	Cutoff trenches/sump
	Temporary vater supply provided	Subsurface cutoff vall
	Permanent water supply provided	Barrier wall constructed
	Spilled material removed	Capping/covering
	Contaminated soil removed	Bulk tankage repaired
	Vaste repackaged	Grout curtain constructed
	Turke diamond alexahene	Bottom sealed
	On-site burial	Gas control
	In situ treatment	Fire control
	Encapsulation	Leachate treatment
	Emergency vaste treatment	Area evacuated
	Cutoff valls	Access to site restricted
	Emergency diking/surface	Population relocated
	vater diversion	-
	Other remedial and enforcement activ	
Ref	erences:,,	
8.	Additional Site Information: DA	RCRA Transaction was completed
	at this site on 12-4-81. The fac	it to also reported as very clean
	and organized, (1) In 1981 the	facility changed ownership from
	Comerco Inc. to Clorox Inc. (3)	Olympic Stain's Paint studge
	waste is shipped to Sheffield /4.	S. Ecology and their solvent
	waste is sent to Latox/Radco.	(4) The deputy chief of the
	City of Batavia Fire Dept. States	
	community or environment due to	o tire or explosion hazard at
	_	1th the sites elegaliness and
	efficiency.	
Daf.	erences: 2 . 9 .	10 . 11 .
ver.		<u>'</u> '
9. 1	Documented and Alleged Target Compou	unds .
	Dogumental and allered toward are	
	Documented and alleged target com	pounds are compiled in Table 1.
	The documented target compounds a from previous sampling projects. I	the supported by analytical data
	based on the history of site operat	tions and professional inference
	Documented and alleged target compound	ind locations are shown on Pi
	2, located in Section 2.	me rocacions are such on tighte

# 8. Additional Site Information continued

- (5) Groundwater flow is assumed to be toward the SW.
- (a) There are 11 municipal wells serving the cities of St. Charles, Geneva, Batavia and West Chicago within a 4 mile radius of the Site. These municipal wells range from 1100 to 2300 feet deep and are open to the Cambrian Ordovician aguifer. This aguifer is not the one of concern for this site because of the depth of the wells along with the presence of two shale confining layers, each 35-100 feet thick.

(Ref #1) The aguifer of concern at this site is the Silurian System consisting mainly of dolomite 50-150 feet below ground level.

(8) Olympic Stain held a NPDES permit to discharge non-contact cooling water into the Fox River from 1977-1982. It is assumed that this discharging of cooling water Ceased in 1982 because the Site does not currently possess a NPDES permit. If the exact outfall location at the Fox River can be determined during the interview with the facility manager, 3 sediment samples will be collected. See Fig. 3b for approximate sampling locations:

	CMPND	STATUS			М	ATRI	x (1	1		DOCUMENTED COMPOUND AND CONCENTRATION	REFERENCE
LOCATON	DOCU	ALLEG	SOIL	SED	GW	SY	AIR	WSTE 0	THR	OR ALLEGED COMPOUND AND RATIONALE	(18) 61/6//25
A		L	V	~	v					cadmium	8
A		~	V	~	~		•			lead (Pho Pb.04)	8
A		1	V	7	7					xylene toluene formalde hyde trichloroethylene	3,8 3,8
A		V	~	2	V					toluene	3,8
<u>A</u>		V	~	_	<u></u>	<u> </u>				formaldehyde	<u>ව</u> වි
<u>A</u>			1	~	"					trichloroethylene	
A		1	1	1	~					Phenolics	<u>ලි</u> 8
A			1	~	_					Phenolics Methyl ethyl Ketone Silicone	
A			V	~	1					silicone	8
A			V	~	4					Styrene	8
A		V	_	"	~					isobutylene	පි
							<u> </u>				
_ <u></u>											
<del></del>											
								-			
		<del></del>						<del>                                     </del>	_	#	
							<b> </b>	<b>  </b> -	_		
								<u> </u>			
							<u> </u>				

Table 1
DOCUMENTED/ALLEGED TARGET COMPOUND LIST

### C. PRELIMINARY/PROJECTED HRS SCORES

The purpose of this section is to:

- o Prepare a preliminary HRS 1 score based on existing file information; and
- o Prepare projected ERS 1 scores based on experience and professional judgement.

PRELIMINARY HRS SCORE (this score is based on existing file information that was obtained prior to the screening site inspection):

PROJECTED HRS SCORE FOR A SCREENING SITE INSPECTION (this score is based on the expected acquisition of information from the screening site inspection):

$$s_{H} = 17.34$$
  $s_{FE} = s_{DC} = 50.00$ 

PROJECTED HRS SCORE FOR A LISTING SITE INSPECTION (this score is based on the expected acquisition of information from the Listing Site Inspection):

HRS 1 score worksheets are located in Section 3.

#### D. HRS 2 PACTOR VALUES

The HRS 2 factor values were computed using HRS 2 (Federal Register proposed date, April 1988) criteria. The HRS 2 factor value criteria were developed to reflect anticipated key HRS 2 scoring issues. The HRS 2 factor values have been calculated using available file information.

	•		Observ <b>e</b> d
Factor	Factor Score	<u>.</u>	Human Exposure
			<b>(X)</b>
Vaste Characteristics	30.0	(100)	
Air Pathway	7.5	(100)	
Groundwater Pathvay	29.1	(100)	none documented
Surface Water Pathway	10.0	(100)	
On-site Pathway	70.0	(100)	
TOTAL HRS 2 PACTOR VALUE	146.6	_ (500)	

DPC 7 FAREAR --- 1 ... . . . .

#### E. VORK SUMMARY

Based on the preliminary and projected HRS scores, a site inspection will be performed.

The objectives of the site inspection are to:

- o Provide information to satisfy BRŞ data gaps;
- o Develop the information base needed to permit U.S. EPA to evaluate the need for future site activities; including: immediate removal measures, additional investigation, or no further action; and
- o Characterize hazardous substances, pollutant dispersal pathways, types of receptors, facility management practices, and potentially responsible parties.

Specific tasks to be conducted during the site inspection are (check all that apply):

	aphs of site and with safety instrer, radiation detronmental samples eed for Immediate	surrounding a umentation (i ector, cyanid Removal Acti	i.e.,ENU, OVA, O <sub>2</sub> i le detector)	neter,
Georphysicst:	10 (0110 (1011		(Specify)	<b>\</b>
OTHER*:				,
	<del></del>			
<del></del>	<del></del>			
			<del></del>	
<del></del>		<del></del>	<del></del>	
* Rationale for thes	se activities and	their impact	on ERS data gaps	:
<del></del>	·			
******		- <del></del>		<del></del>
		•		

### F. PROPOSED SAMPLE PLAN

The HRS data gaps are identified in this section, and a proposed sample plan is developed based on the type of information required.

B) Sampling proposed to satisfy HRS data gap(s):  Soil Sediment GV SV Air Vaste  C) Sampling procedures (number and types of samples; equipment; methodology): Eight Shallow Soil samples, including the post of the samples of samples of samples, including the post of the sampling will be determined a visual inspection of the sampling beating will be determined a visual inspection of the sampled as per standard EPA prosection with a garden trowel deeps with a post hole digger.  A table of proposed sample descriptions is presented in Table 2, Section 1. A proposed sample location map is presented in Figure 3a, in Section 2.  A) HRS data gap(s): Observed Telease to groundwater  B) Sampling proposed to satisfy HRS data gap(s):  Soil Sediment GV SV Air Vaste  C) Sampling procedures (number and types of samples; equipment; methodology): Three residential well samples will be collected one will be an upgradient potential bockground sample. A samples will be oblighed from the after running the water is minutes. Also a duplicate residential well sample and distinuator field blank will be analyzed.	A)	ERS data gap(s): Waste Characteristics
C) Sampling procedures (number and types of samples; equipment; methodology):  Eight Shallow Soil Samples, (ncluding one to be used as a potential background Sample, will collected. The exact sampling locations will be determined a Visual inspection of the site is Made. All samples (Soil, Gill) will be packaged and shipped as per standard EPA prostables will be collected with a garden frome! deeps with a post hole digger.  A table of proposed sample descriptions is presented in Table 2, Section 1. A proposed sample location map is presented in Figure 3a, in Section 2.  A) HRS data gap(s):  Soil Sediment GW SW Air Waste  C) Sampling procedures (number and types of samples; equipment; methodology): Three residential well samples will be collected one will be an upgradient potential bockground sample. Samples will be collected to make a types of samples will be collected to make a sample.  Samples will be collected from taps after running the water 15 minutes. Also a duricate residential well sample and difficults.	B)	
methodology): Eight Shallow Soil samples, including one to be used as a potential background Sample will Collected. The exact sampling locations will be determined a Visual inspection of the site is made. All samples (Sil.) Gill be packaged and shipped as per standard EPA proshallows will be Collected with a garden trowel deeps with a post hole digger.  A table of proposed sample descriptions is presented in Table 2, Section 1. A proposed sample location map is presented in Figure 3a, in Section 2.  A) HRS data gap(s): Observed Telease to groundwater  B) Sampling proposed to satisfy HRS data gap(s):  Soil Sediment GV SV Air Vaste  C) Sampling procedures (number and types of samples; equipment; methodology): Three residential well samples will be collected. One will be an upgradient potential background sample. Samples will be collected from taps after running the water 15 minutes. Also a duelicate Cesidential well sample and dusting the collecter of the sample of the collecter of the		SoilSedimentGVSVAirVaste
Section 1. A proposed sample location map is presented in Figure 3a, in Section 2.  A) HRS data gap(s): Observed Telease to groundwater  B) Sampling proposed to satisfy HRS data gap(s):  Soil Sediment GV SV Air Vaste  C) Sampling procedures (number and types of samples; equipment; methodology): Three residential well samples will be collected One will be an upgradient potential background Sample. A samples will be collected from taps after running the water 15 minutes. Also a dualitate residential well sample and difficulties.	C)	methodology): Eight Shallow Soil samples, including one to be used as a potential background Sample, will collected. The exact sampling locations will be determined a visual inspection of the site is made. All samples (Soil, GW) will be packaged and shipped as per standard EPA proschallows will be collected with a garden trowel deeps with a
In Section 2.  A) HRS data gap(s): Observed release to groundwater  B) Sampling proposed to satisfy HRS data gap(s):	A	table of proposed sample descriptions is presented in Table 2,
In Section 2.  A) HRS data gap(s): Observed Telease to groundwater  B) Sampling proposed to satisfy HRS data gap(s):	Sec	tion 1. A proposed sample location map is presented in Figure 3a,
B) Sampling proposed to satisfy HRS data gap(s):		
Soil Sediment GV SV Air Vaste  C) Sampling procedures (number and types of samples; equipment; methodology): Three residential well samples will be collected one will be an upgradient potential background sample. I samples will be collected from taps after running the water 15 minutes. Also a duclicate residential well sample and distinctions.	<b>A)</b>	irs data gap(s): observed release to groundwater
C) Sampling procedures (number and types of samples; equipment; methodology): Three residential well samples will be collected One will be an upgradient potential background sample. I samples will be collected from taps after running the water 15 minutes. Also a ducticate residential well sample and distinctions.	B) :	Sampling proposed to satisfy HRS data gap(s):
one will be an upgradient potential bockground sample. I samples will be collected from taps after running the water 15 minutes. Also a ductionte residential well sample and distinctions.		SoilSedimentGVSVAirVaste

Section 1. A proposed sample location map is presented in Figure 3b, in Section 2.

Note: Sample locations and/or the number of samples may be changed or eliminated at the discretion of the site team leader in response to actual site conditions during the course of the inspection.

### F. PROPOSED SAMPLE PLAN (Continued)

The HRS data gaps are identified in this section, and a proposed sample plan is developed based on the type of information required.

0

in Section 2.

3	A)	HRS data gap(s): Observed release to surface water
	B)	Sampling proposed to satisfy HRS data gap(s):
		Soil/ SedimentGVSVAirVaste
	C)	Sampling procedures (number and types of samples; equipment; methodology): Olympic Stain discharged non-centact cooling water into the Fox River from 1977-1982. If the location of the outfall can be determined, 3 sediment samples will be collected. One will be at the point when the outfall enters the Fox River one will be downstream from this point, and the third will be an upgradient potential background sample. No actual Surface water samples will be taken.
	A	table of proposed sample descriptions is presented in Table 2,
	Sec	ction 1. A proposed sample location map is presented on Figure 3b,
	in	Section 2.
4	A)	HRS data gap(s): observed release to the atmosphere/ possibility of fire and/or explosion hazard.
	B)	Sampling proposed to satisfy HRS data gap(s):
		SoilSedimentGVSVAirVaste
	C)	Sampling procedures (number and types of samples; equipment; methodology): These data gaps will not be evaluated during the SSI. This decision is based on IEPA and USEPA file information and a discussion with the deputy chief of the City of Batavia Fire Department. If anditions have changed, these areas will be addressed during the LSI.
	A	table of proposed sample descriptions is presented in Table 2,

Sample locations and/or the number of samples may be changed or eliminated at the discretion of the site team leader in response to actual site conditions during the course of the inspection.

Section 1. A proposed sample location map is presented in Figure 3,

			M	IATRI	X (1	5		RATIONALE FOR DETERMINING SAMPLE LOCATION	PARAMETERS 1								
LOCATION	SOIL	SED	GW	sw	AIR	WSTE	ÓTKR		A/B/N	Pest/ PCB	VOA	METAL	CN-	OTHER			
SI	v							waste characteristics:	V	~	~	-	-				
SZ	v							waste characteristics	V	~	~	-	-	<del></del>			
53	0							waste characteristics	~	~		-	~				
<b>S</b> 4	0							waste characteristics	V	~	~						
<b>S</b> 5	V							waste characteristics	U	V	V						
SG	V							waste characteristics	V	ارد	-	-	~				
<b>S</b> 7	~							waste characteristics		1	~	-	\				
SB	V							Potential background	V	V	V	V	4				
59		V						Contamination of surface water	~	-	- 1	-	-				
SID		1						contamination of surface water	~	~	v	~	4				
SII		V						potential background	V		~	-	~				
GWI			/					contamination of groundwater	<b>U</b>	۰	- "	~					
GWZ			1						1	L			-				
GW3			V					contamination of ground water potential background	~	~	~	-	-				
Duplicate			1					duplicate of a residential well sample	<u></u>	~	-						
Field Blank					·		V	distilled water field blank	~	1		-	U				
ارداری و <del>دادی به مطابق با آرا</del> یه م														<			
					'y									1			
TOTALS	8	3	4	0	0	0											

<sup>1</sup>Target Compound List Attached

Table 2
PROPOSED SAMPLE DESCRIPTIONS
(INCLUDING ALL LABORATORY BLANKS AND DUPLICATES)

# G. COMMENTS

	None
	H. HEALTH AND SAFETY
	posed E & E Health and Safety protocol to be followed during site
ins	pection.
1.	Anticipated level of protection: A B C D
2.	Level of protection modifications: Will enter site in level D with a possible upgrade to level C if monitoring
	equipment detects an increased hazard.
3.	Work limitations (time of day, etc.): Work will be limited to daylight hours only. Monitor team members for hart
	or cold stress and observe the buddy system.
	I. TYPE OF DELIVERABLE
	Proposed report format to be submitted to U.S. EPA.
1.	SSI Report including U.S. EPA 2070-13 Form
2.	Letter Report
036:	5:3

						,			·····	,	SUB	rask								***************************************	·····		
	SUBTASK CUDE	General Non-Specific	File Search/Review	Work Plan	Safety Plan	QAPP	Mobilization/Demobilization	Travel	Non-Sampling Field Work	Sample Management	Field Sampling	Screening/Analytical	Subcontract	Meteorologic/Air Sampling Studies	Geophysical Work	Hydrogeological Work	Data Processing/Modeling	Data Yalidation	Draft Final Deliverable	Internal QA Review	Final Deliverable	Respond To Comments	•
		A	B	С	D	Ε	F	G	Н	1	J	×	L	М	N	0	P	Q	R	S	Т	כ	TOTAL
TEAM LEADER		12	12		8		4	4	8		16								60		20	B	152
SAFETY OFFICER							4	4	8		16		·										32
SAMPLER								4		20						•							24
TE AM MEMBER							4.	4	8		16		<del></del>										32
TEAM MEMBER									·														
Admin.		2								4								-					6
Edit/Publ.																			15		5		20
ŲΑ					8													6		45			59
TOTALS FOR PROJE	ст	14	12		16		12	16	24	24	48							6	75		25	8	325

# J. ESTIMATED LOE HOURS

SUMMARY OF PROJECTED HOURS NEEDED TO IMPLEMENT SITE INSPECTION AND COMPLETE SITE INSPECTION REPORT.


# SITE MAPS

ď-

# SITE MAPS

- 1. SITE LOCATION MAP (TOPO)
- 2. DOCUMENTED/ALLEGED
  TARGET COMPOUND MAP
- 3. PROPOSED SAMPLE LOCATION MAP

	ology and environ		<del></del> .
TITLE		FIGURE #	
aire		SCALE	<del></del>
CITY	STATE	F.A.N.	<del></del>
SOURCE	<del></del>	DATE	
	1	REVISED	



SOURCE: Ecology and Environment, Inc., 1988; BASE MAP: USGS Aurora North, IL Quadrangle, 7.5 Minute Series, 1964; Geneva, IL Quadrangle, 7.5 Minute Series, 1964.







FIGURE 1 SITE LOCATION MAP







SOURCE: Ecology and Environment, Inc., 1988; BASE MAP: USGS Aurora North, IL Quadrangle, 7.5 Minute Series, 1964; Geneva, IL Quadrangle, 7.5 Minute Series, 1964.

LEGEND
groundwater sample
(residential well)

O SCALE 0 0.5 1 MILE

FIGURE 3b PROPOSED SAMPLE LOCATION MAP

# HRS WORKSHEETS

Hazard Ranking System 1: Score Worksheets:

# PRELIMINARY AND PROJECTED HAZARD RANKING SYSTEM SCORE WORKSHEETS

Site Name:	COMERCO IN	UC. OLYMPIC STA	IN DIV.	_(Cerdis Name)
	None			_(AKA)
Address:	1020 049	IMPIC DRIVE		
City/Count//St	ate/Zip BATAU	IA/KANE/ILL	INDIS/60:	510
Cerdis ID #	ILD085224	186	SSID No	NE
Prepared by	BILL SCHAE	FER E&E	Date 7-2	1-88
Reviewed by	m mast	E&E	Date $\frac{9}{}$	15/88
TQO:	F05-B711 -0	48	PAN FIL	•
WP-SS WP-LS	eassessment Sl		• ••	
S <sub>M= 0.0</sub>	00	S <sub>FE</sub> =	S <sub>DC</sub> =	0.00
PROJECTED	HRS SCORE	FOR SCREENIN	g site insp	PECTION (SSI)
S <sub>M</sub> = 17	.34	S <sub>FE</sub> =	S <sub>DC</sub> =	50.00
PROJECTED	HRS SCORE	FOR LISTING S	ITE INSPECT	TION (LSI)
S <sub>M</sub> = 27	7.84	S <sub>FE</sub> =	S <sub>DC</sub>	50.00

#### PRELIMINARY HRS SCORE

THIS SCORE IS SASED ON EXISTING FILE INFORMATION THAT WAS DETAINED PRIOR TO THE SCREENING SITE INSPECTIONAL

	s	s'
Groundwater Route Score (Sou-)	0	0
Surface Water Route Score (Sp)	0	0
Air Route Score (S <sub>A</sub> -)	-	-
Sow + Stw + SA		0.
V S + S + S + S + S + S + S + S + S + S		0
$\sqrt{s_{qw}^2 + s_{qw}^2 + s_A^2} / 1.73 - s_M$		0

### PROJECTED HRS SCORE FOR SCREENING SITE INSPECTION (SSD

(THIS SCORE IS SASED ON THE EXPECTED ACQUISITION OF INFORMATION FROM THE SCREEMING SITE INSPECTIONAL

	S	S.
Groundwater Route Score (S <sub>ee</sub> -)	28.26	798.63
Surface Water Route Score (Sp)	10.07	101.40
Air Route Score (S <sub>4</sub> -)		_
Sour + Sour + SA		900.03
V Som + Som + SA		30.00
VS. + S. + S. / 173 - SM-		17.34

### PROJECTED HRS SCORE FOR LISTING SITE INSPECTION (LSD

(THE SCORE IS SASED ON THE EXPECTED AGUSTION OF INFORMATION FROM THE LISTING SITE INSPECTION.)

	S	8.
Groundwater Route Score (S)	47.10	2218.41
Surface Water Route Score (S <sub>ee</sub> -)	10.07	101.40
Air Route Score (S <sub>a</sub> -)	_	
S. + S. + S.		2319.81
V Sow + Sow + SA		48.16
$\sqrt{S_{ou}^2 \cdot S_{ou}^2 \cdot S_A^2} / 1.73 - S_M -$		27.84

# GROUNDWATER ROUTE

PRELIMINARY HRS SCORE WORKSHEET  (This score is based on existing file information that was obtained					
Rating Factor	prior to the Scree Assigned Value (Circle One)	Multi- plier	Score	on.1 Description	Ref. #
1 Observed Release	(o) 45	. xt	<del></del>	none documented	·
# Observed Release soon	If Observed Release scores 45 proceed to line 4 If Observed Release scores 0 proceed to line 2				
2 Route Characteristics				Aquiler Description:	
				SilurianDolomite	1
Depth to Aquiter of concern	0 1(2)3	12	4	5·1 a.	1
Net Precipitation	0 1) 2 3	x1	1	Precip 33.6" Evap 29.5"	4
Permeability of the Unsaturated Zone	0 1 2 3	x1	1	10 <sup>-7</sup> cru/sec	
Physical State	0 1 2/3	<b>x1</b>	3	liquid	3
} 	Total Route Char. Score	•	9		
3 Containment	<u>(0)</u> 1 2 3	хI	0	unknown.	
Waste Characteristics Persistence (0)					
	1 2 3 0 0 0 6 9 13				
2 6 3 9	6 9 12 9 12 15 12 15 18	x1	0	uxkrown	•
	@12345678	x1	0	unknown	
<u></u>	Total Waste Char, Scor	re	0		
S Targets	^	4			
Groundwater Use Distance to Nearest Well	0 1 2 3 4	x3	9	drinking water	1 -
Nearest Well 0	0 0 0 0 0 0 0 0 4 6 8 10		ļ		
Population Served	0 8 12 (16) 20	1	<del> </del>	Pop ~ 675	6
šl	0 12 18 24 30 0 16 24 32 35 0 20 30 35 40	. x1	16	well N /2 mile	1
1	Total Targets Score		25		
6 If line 1 is 45, multiply If line 1 is 0, multiply	0 x 0 x 0 x 5		0		
Divide line (d by s	7,330 and multiply by 100	,	S <sub>ow</sub> =	0	

### **GROUNDWATER ROUTE**

PROJECTED HRS SCORE WORKSHEET FOR SCREENING SITE INSPECTION (SSI)					
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	om the Screening Site Insp  Description	Ref. #
1 Observed Release	<b>(6)</b> 45	, x1		no monitoring wells	
# Observed Release so	ores 45 proceed to fine 4	<del></del>	L		
2 Route Characteristics				Aquiler Description:	
•				Silurian Dolomite	1
Depth to Aquiler of concern	0 1/2/3	12	4	51 n.	. 1
Net Precipitation	0 1 2 3	xi	1	Precip 33.6" Evap 29.5"	4
Permeability of the Unsaturated Zone	0 102 3	хí	1	10 <sup>-7</sup> cm/sec	1
Physical State	0 1 2 3	ส	3	liquid	· 3
•	Total Route Char. Score		9		
3 Containment	0 1 2(3)	xi	3	assume leaky drums	3
Waste Characteristics					
Persistence 0 Toxicity 1 3	1 2 3			lead ordinium	
2 6 3 9	6 9 12 9 12 15 12 15 (8)	x 1	18	toluene xylene assumed	8,3
Haz. Waste Quantit		, x1	6	2540 drums	3.
	Total Waste Char. Scor	•	24		
5 Targets	2				
Groundwater Use Distance to Nearest Well	0 1 2 3	x3	9	drinking water	1 -
0	0 0 0 0 0				
Population 3 Served 3	0 8 12 16 20 0 12 18 24 30		<del></del>	Pop ~ 675	6
5	0 16 24 32 35 0 20 30 35 40	<b>x</b> 1	16	well ~ /2 mile	1
	Total Targets Score		25		
6 # fine 1 is 45, multiply # line 1 is 0, multiply		•	16200		
Divide line (d by 57,330 and multiply by 100 Sgw <sup>m</sup> 28.26					

### **GROUNDWATER ROUTE**

PROJECTED HRS SCORE WORKSHEET FOR LISTING SITE INSPECTION (LSI)  (This score is based on the expected aquisition of information from the Listing Site Inspection.)					
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Observed Release	0 (45)	. x1	45	assumed release	
If Observed Release soon	ores 45 proceed to fine 4				
2 Route Characteristics		<del></del>		Aquiler Description:	
	·				
Depth to Aquiler of concern	0123	12		. ft.	
Net Precipitation	0 1 2 3	x1		Precip Evap	
Permeability of the Unsaturated Zone	0 1 2 3	xi		cm/sec	
Physical State	0123	x1			
	Total Route Char, Score	•			
3 Containment	0123	xi	-		
4 Waste Characteristics	^			cadmium,	
Persistence 0	1 2 (3)			Xylene toluene.	
Toxicity 1 3	6 9 12 9 12 15 12 15 48	<b>x1</b>	18	lead ossumed	3,8
Haz. Waste Quantity	012345678	x1	6	2540 drums	3
	Total Waste Char, Scot	• •	24		
S Targets					
Groundwater Use	0 1 2/3	· x3	9	drinking water	1-
Distance to Nearest Well	0 0 0 0 0				
Population 3	0 4 6 8 10 0 8 12 16 20 0 12 18 24 30			POP ~675	6
Served 4	0 16 24 32 35 0 20 30 35 40	x t	16	well ~ //2 mile	1
	Total Targets Score		25		
6 If line 1 is 45, multiply If line 1 is 0, multiply	1		27000		
Divide line d by 57,330 and multiply by 100 Sow= 47.10					

# SURFACE WATER ROUTE

PRELIMINARY HRS SCORE WORKSHEET  (This score is based on existing file information that was obtained prior to the Screening Site Inspection.)					
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Observed Release	0 45	x 1	0	none documented	
II Observed Release so	ores 45 proceed to line 4	Г <u>,</u>			
2 Route Characteristics	Integraning Terrain	•		Facil ≤3%	6
Faci	000003	. x1	0	Interv 1.2 %	6
Stop	0 1 2 2 3		<u> </u>		
1-yr. 24 hr Rainfal	• •	x 1	2	2.45 in.	4
Distance to Nearest		x2			
Surface Water Physical State	0 1 2 3	x 1	2	Fox Piver	9
Filysical State			7	ligvid	3
	Total Route Char. Score	) 	/		
3 Containment	(0)1 2 3	x1	0	unkrown	
4 Waste Characteristics					
Fersistence (0) Toxicity (1)	0 0 0				
1 216	6 9 12 9 12 - 15 12 15 18	. x1	0	Unkrown	
• • • • • • • • • • • • • • • • • • • •	12 15 16 (0) 1 2 3 4 5 6 7 8	x1	0	unkrown	
	Total Waste Char. Scor	19	0		
S Targets	·		<u> </u>		
Surface Water Use	0 1/2 3	x3	7	T. C. of the	
Dist. to Sensitive Environment	0 1 2 3	~ 9	3	Fox Per Tarrection	1 17
Environment	Distance to Water lotake Downstream	~~	$\mathcal{U}_{-}$	nore	6.7
	0 0 0 0 0 .				
Population Served	10 12 18 24 30	1	<del></del>		
	0 16 24 32 35 0 20 30 35 40	x1		no irakes	
	Total Targets Score		6		
6 # Eine 1 is 45, multiply # Eine 1 is 0, multiply			0		
la .			L		
Divide line (d) by 64,3	50 and multiply by 100	Ssw	0		

# SURFACE WATER ROUTE

PROJECTED HRS SCORE WORKSHEET FOR SCREENING SITE INSPECTION (SSD					
(This score is based on i	the expected acquisition	n of Info	rmation f	rom the Screening Site ins	pection.)
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Observed Rolease	0 (45)	x t	45		
t Observed Release soor t. Observed Release soor					
2 Route Characteristics	ntervening Terrain	•		Facil %	
Facilo	0 0 0 0 3 ly 0 1 1 2 3	x t		Interv %	
Stope	0 1 2 2 3 0 2 2 3 3 0 2 3 3 3 3	·			
1-yr. 24 hr Rainfall	0123	x1		in.	
Distance to Nearest Surface Water	0123	x2		•	
Physical State	0123	<b>x1</b>			
	Total Route Char, Score				
3 Containment	0123	g1			
4 Waste Characteristics					
Persistence 0 1	2 3			codmium lead	
Toxicity 1 3	9 12	x1	18	toluane, xylene assumed	3,8
Haz. Waste Quantity	0 1 2 3 4 5 6 7 8	x1	6	2540 drums .	3
	Total Waste Char. Sco	10	24		
S Targets	<u> </u>		<u> </u>		
Surface Water Use	0 1/2/3	. x3	6	Fox liver recreation	
Dist to Sensitive ( Environment	0 1 2 3 Distance to Water	<b>x</b> 2	0	none	6,7
	Intake Downstream	•			
Population	0 4 6 8 10 0 8 12 16 20				
Served	0	x t	0	no intakes	
	Total Targets Score		6		
6 K line 1 is 45, multiply E line 1 is 0, multiply			6480		
Divide line ( by 64,350 and multiply by 100 S <sub>sw</sub> 10.07					

# SURFACE WATER ROUTE

PROJECTED HRS SCORE WORKSHEET FOR LISTING SITE INSPECTION (LSI)						
(This score is based on	(This score is based on the expected equisition of information from the Listing Site inspection.)					
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Cescription	Ref. #	
1 Observed Release	0 (45)	x 1	45			
M Observed Release score M Observed Release score	res 45 proceed to line 4 res 0 proceed to line 2	:				
2 Boute Characteristics	Intervening Terrain	•		Facil %		
Facili	0 0 0 0 3 av 0 1 1 2 3	x t	·	Interv %		
Stope	114 4 4 4 4	•				
1-yr. 24 hr Rainfall	0123	x 1		ir.		
Distance to Nearest Surface Water	0 1 2 3	×2		•		
Physical State	0123	x 1				
	Total Route Char, Score					
3 Containment	0123	x1				
Waste Characteristics	- 0					
Persistence 0 1 Toxicity 1 3 6	1 2 <del>23</del> 0 0 0 5 9 12		,	heavy metals, xylore		
Toxicity 0 0 0	5	×1	18	tolvere assumed	3,8	
Haz. Waste Quantity	012345678	×1	6	2540 drums	3	
	Total Waste Char, Score		24			
S Targets ,	^	•				
Surface Water Use	0 1(2)3	<b>x</b> 3	6	Fox River recreating		
Dist. to Sensitive ( Environment	0)1 2 3 Distance to Water	×2	0	none	6,7	
<b>i</b>	Intake Downstream 0 0 0 0 0 0 4 6 8 10		,			
Population Served	0		·			
	0 16 24 32 35 0 20 30 35 40	×1	0	no intakes		
	Total Targets Score		6			
6 If line 1 is 45, multiply If line 1 is 0, multiply	2x 8x 4x8		6480			
Oivide line ( by 64,350	I and multiply by 100	S <sub>sw</sub> =	10.0	7		

#### AIR ROUTE

	PRELIMINARY HRS score is based on existing prior to the Scri	ng file inf	ormation	that was obtained	
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
Observed Release	0 45	x1			
t kne 1 is 0, the Satine 1 is 45, then p	roceed to line 2	•			
Reactivity & Incompatability	0 1 2 3	x 1			
Toxicity .	0 1 2 3	x3			
Haz. Waste Quardin	0 1 2 3 4 5 6 7 8	x i			
3 Targets  Population within 4-mile Radius  Distance to Sensitiv Environment  Land Use	Dist to Population  O O O O  9 12 15 18 12 15 18 21 15 18 21 24 18 21 24 27 21 24 27 30  O 1 2 3  Total Targets Score	x 1 x 2 x 1			
existiply (1 x 2 x (	<u> </u>				
Divide line 4 by 35,	100 and multiply by 100		S <sub>a</sub> =		!

There is insufficient information to score this route at this time.

ļ

not scored ...

# AIR ROUTE

Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref.
1 Observed Release	0 45	x1			
If line 1 is 0, the Sa=0 If line 1 is 45, then pro					
2 Waste Characteristics			•		
Reactivity & Incompatability	0 1 2 3	x 1			
Toxicity .	0 1 2 3	, x3			
Haz. Waste Quantity	0 1 2 3 4 5 6 7	8 x1			
•	Total Waste Char.	Score			
3 Targets Population within 4-mile Radius Po	Dist to Population  0 0 0 0  9 12 15 18 12 15 18 21 P-15 18 21 24 18 21 24 27				
Distance to Sensitive Environment	21 24 27 30 0 1 2 3	x1 x2	<del></del>		-
Land Use	0 1 2 3	x 1			T
	Total Targets Scor	•			
4 stutioty [] x 2 x 2					

There is insufficient information to score route at this time.

# AIR ROUTE

				G SITE INSPECTION (LS	_
(This score is based			xmation	from the Usting Site Inspe	ection.)
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
Observed Release	0 45	x1			
tf line 1 is 0, the Sa If line 1 is 45, then	=0. Enter on line 5 proceed to line 2	·			
2 Waste Characteristics	s		•		
Reactivity & Incompatability	0 1 2 3	x1			
Toxicity	0 1 2 3	<b>x</b> 3			
Haz. Waste Quanti	ty 0 1 2 3 4 5 6 7 8	x1		•	
•	Total Waste Char. So	ore			
3 Targets Population within 4-mile Radius	Dist to Population  0 0 0 0  9 12 15 18  12 15 18 21  Pop 15 18 21 24  18 21 24 27	x1			
Distance to Sensitin Environment	121 24 27 30	x2			
Land Use	0 -1 2 3	x t			
	Total Targets Score				
(C) ecotricity (1 x (2 x (	3	_			
Divide line 4 by 35	,100 and multiply by 100		S <sub>2</sub> =		

There is insufficient information to score air route at this time.

# FIRE AND EXPLOSION

	Assi					507 B	ening Si Multi-		1	
Rating Factor	(Ci	rde	On	e)			plier	Score	Description R	lef. #
1 Containment	0		3				, <b>x</b> 1			
2 Waste Characteristics							:			
Direct Evidence			3				x t	•		
<b>I</b> gnitability (	1	2	3				x 1		,	
Reactivity .	) 1	2	3				. x1			
Incompatability	) 1	2	3				x 1		4 -	
Haz. Waste Quantity	0 1 2	2 3	4	5 6	5 7	8	<b>x1</b>			
	Tota	ı w	aste	Ch	ar,	Scor	•			
3 Targets		•								
Dist. to Nearest Pop.	0	1	2	3	4	5	x 1			
Dist. to Nearest Bldg.	0	1	2	3			x 1			
Dist. to Sensitive Env.	0	1	2	3			x 1			
Land Use	0	1	2	3			x 1			
Pop. Within 2 miles	0	1	2	3	4	5	x 1			
Bldgs. Wahin 2 miles	0	1	2	3	4	5	x 1		•	
	Tot	al T	arge	els :	S∞	re				
Multiply [] x 2 x 3										

Fire and Explosion not scored based on conversation with the Deputy Chief of the Batavia Tire Dept.

# FIRE AND EXPLOSION

(This score is based on					mation f	rom the Screening Site Ins	pection.1
Rating Factor		gned Value rde One)		Multi- plier	Score	Description	Ref. #
1 Containment	0	3		x1			<u> </u>
2 Waste Characteristics		•					
Direct Evidence	0	3		<b>x</b> 1			
Ignitability	0 1	2 3		<b>x1</b>			
Reactivity .	0 1	2 3		<b>x</b> 1			
Incompatability	0 1	2 3		x t			
Haz. Waste Quantity	012	3 4 5 6	7 8	x1			
3 Targets ·	Tota	! Wase Ch	ar. So	οxe			
Dist. to Nearest Pop.	0	1 2 3	4 5	, ×1			
Dist. to Nearest Blog	- 0	1 2 3		x 1	٠		
Dist. to Sensitive En	v. 0-,	1 2 3		· xt			
Land Use	0	1 2 3		x 1			
Pop. Within 2 miles	0	1 2 3	4 5	<b>x</b> 1			
Bldgs. Within 2 miles	0	1 2 3	4 5	x t		•	
•	Tota	il Targets S	S∞re				
Muttiply [] x 2] x [3	}						

Fire and Explosion not scored based on conversation with the Defuty Chief of the Batavia Five Dept.

# FIRE AND EXPLOSION

			Value			ulti-	Score	from the Usting Site Insp	<del></del>
Rating Factor		irde			<u> </u>	lier	Swie	Description	Ref.
1 Containment	0		3			<b>x1</b>		İ	
2 Waste Characteristics	;			•					
Direct Evidence	0		3			x 1			
Ignitability	0 1	2	3			x t			
Reactivity	0 1	. 2	3			x 1			
Incompatability	0 1	2	3			x1			
Haz. Waste Quantit	y 0 1	2 3	450	5 7 1	6	x1		1	1
3 Targets	Tot	al Wa	ste Cl	ar. S	core				
Dist. to Nearest Pop	o. 0	1	2 3	4	5	x 1	<del></del>		
Dist. to Nearest 81d	g. 0	1	2 3			<b>x</b> 1			1
Dist to Sensitive E	nv. 0	1	2 3			<b>x</b> 1			
Land Use	0	1	2 3			<b>x</b> 1			
Pop. Wishin 2 miles	0	1	2 3	4	5	K 1			
Blogs. Wahin 2 mile	s 0	1	2 3	4	5	z i		• •	<b> </b>
	To	al Ta	rgets	Score	)				
Multiply [] x 2 x {	3								

Fire and Explosion not scored based on conversation with the Deputy circled the Batavia Fire Dept.

DIRECT CONTACT

	PRELIMINARY HRS				
CThi	ls score is based on existing prior to the Scre				
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Cescription	Ref. #
1 Observed Incident	<b>6</b> 45	x1	٥	nore documented	
If line 1 is 45, proc If line 1 is 0, proce	eed to line 4				
2 Accessibility	0 1 2 3	<b>x1</b>	0	urknown	
3 Containment	0 (15)	x 1	15	drums	3
Waste Characteristic	cs				
Toxicity .	<b>0</b> 123	x 5	0	unknown	
S Targets					
Pop. Within 1 mile	0 1 2 3 4 5	x 4	16	~ 3447 people	.6
Dist. to Crit. Habi	lat 0 1 2 3	x 4	0	none	7
	Total Targets Score		16		
6 If line 1 is 45, multip If line 1 is 0, multip	tiply { x4x5  ply { 2x5 x4x5		0		
Divide line 6 by 2	21,600 and multiply by 100	S <sub>(</sub>	r 0		

# DIRECT CONTACT

<b>[</b>				NG SITE INSPECTION (Something Site lines	
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Rei. ¢
Observed Incident	<b>(</b> ) 45	x1	0		
tf line 1 is 45, proce	eed to line 4	•			
2 Accessibility	0 1 2 3	x1	3	assured no fince	
3 Containment	0 (15)	x1	15	drums	3
Waste Characteristic	<b>3</b>				
Toxicity .	0 1 2 3	<b>x</b> 5	15	heavy motals (Pb)	8
S Targets					
Pop. Wahin 1 mile	0 1 2 3 4 5	<b>x</b> 4	16	~ 3447 People	6
Dist. to Crit. Habi	2 3	x4	0	rone	7
	Total Targets Score		16		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
6 If line 1 is 45, multip If line 1 is 0, multip	py [x4xs y 2x0x4xs		10800		
Divide line 6 by 2	1,600 and multiply by 100	S	c• 50	0.00	

# DIRECT CONTACT

				G SITE INSPECTION (LS) from the Wating Site_Inspec	-
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Observed Incident	0 (45)	x1	45	assume incident	
If line 1 is 45, proce	eed to line 4 ed to line 2	•			
2 Accessibility	0 1 2 3	<b>x1</b>	•		
3 Containment	0 15	x 1			·
4 Waste Characteristic	3				
Toxicity .	0 1 2 3	<b>x</b> 5	15	heavy metals assumed	8
S Targets			·		
Pop. Within 1 mie	0 1 2 3 4 5	x4	16	~3447 peosie	6
Dist to Crit. Hz5it	z 6 1 2 3	x<	0	none	7
	Total Targets Score		16		
6 If line 1 is 45, multiple of line 1 is 0, multiple	py 1 × 4 × 5 y 2 × 3 × 4 × 5		10800		
Divide line 6 by 21	1,600 and multiply by 100	s <sub>o</sub>	c 50	0,00	

Hazard Ranking System 2 Factor Value Worksheets

#### HRS 2- PACTOR VALUE

<u>Factor</u>	Factor Value	Observed <u>Human Exposure</u> (X)
Vaste Characteristics	30.0 (100)	
Air Pathvay	7.5 (100)	
Groundvater Pathvay	29.1 (100)	none documented
Surface Vater Pathvay	(100)	
On-site Pathway	70.0 (100)	
TOTAL ERS 2 PACTOR VALUE	146.6 (500)	•

#### WASTE CHARACTERISTICS

		•	Yes	Reference	factor Value
			(x)		
1.	(4)	Are CONTAINERS open, unsealed, or	Und		
			u <u>nk</u>		<u>O</u> (5)
	(D)	Is there evidence of contaminant migration away from the containers:	, NO :	•	0 (5)
	(c)	Is the source(s) unlined or does it	t .		
		have unsound diking?	MNK	<del></del>	(5)
2.	(4)	Does the LANDFILL have exposed			
		waste, or is the landfill uncovered	d.	•	
		or is the landfill covered with			
		contaminated soil, non-intact cover	EA		•
		or cover less than 1 inch?	NA		(5)
	<b>(b)</b>	Is there evidence of contaminant			
		migration away from the source?			(5)
	(c)	Is there an absence of a liner, a			
		run-on or runoff management system or leachate collection and removal		•	
		system?			(5)
				<del></del>	
3.	(4)	Is the SURFACE IMPOUNDMENT wet	•	•	
		and non-enclosed?	NA		(5)
	<b>(b)</b>	Is there evidence of contaminant			
		migration away from the source?		****	(5)
	(c)	Is there no liner or diking?			(\$)
4.	<b>(4)</b>	Is the PILE uncovered, or is the			• ••
		pile covered with contaminated soil	-		
		non-intact cover or cover less than inch?	NA		181
	(b)	Is there an absence of a function-	7		(5).
		ing run-on or runoff management			•
		system or leachate collection			
		system?			(5)
	(0)	Is there an absence of a liner?			(5)
		•			٠.
5.		y answer highest factor value			
		the following questions:			
	(4)	Is constituent data available	LINK		<b>^</b>
	12.	for waste?	<del></del>		
	101	Is waste quantity as deposited information available?	UNK		Ö (8)
	(-1	Is disposable volume known?	<del>un</del> k		
		Is disposable area known?	MERLI		O (2)
			W.Z.	•	

...Continued

#### WASTE CHARACTERISTICS (Continued)

6. Complete the table for all sources at the site. Calculate Waste Quantity score and second summation to a maximum value of 30.

Source	Surface Area (ft2)	٠	Divisor	-	Waste Quantity Score
Pil•		•	85		
Drums/Non-drum Container	12470	•	233	•	53.5
Surface Impoundment		•	375	•	
Land Treatment		·	27,000	-	
Landfill		٠	85,666	_	<u> </u>
Contaminated Soil		٠	1,125,000		•

assume 2½ dia .drum
Surface Area:
(2540drums)(T1/4)(2.5)<sup>2</sup>
= 12470ft<sup>2</sup>

Total 53.5 30 (30max)

Total Waste Characteristics 30 (100)

#### AIR PATHWAT

Factor Tes Value 1. Only assign factor value for (a) or (b), (x) choosing the higher value: (a) Is there a residence or regularly occupied building between 0 to 1/8 mile from a potential source(s)? (b) Is there a residence or regularly occupied building between 1/8 to 2 miles from a potential source(s)? 2. Complete (a) and (b) and assign the higher factor value: (a) If documented contamination of air, enswer yes and assign factor value of 75. (b) Calculate potential population and

Distance (mile)	Population	*	Distance Weighting Factor		Subtotal
Onsite	0	×	1.662	-	0
0-1/4	224.5	×	0.323	-	72.5
1/4-1/2	350,3	×	0.056	-	19.6
1/2-1	2872.4	×	0.017	-	48.8
1-2	12203.6	=	0.005	-	61.0
2-3	10230.6	=	0.003	-	30.7.
3-4	75110 8		0.002		15 1

assign factor value as given below:

e.

Total 247.7 x 1 - 2.5 (75max)

Total Air Pathway Value 7.5 (100)

#### GROUNDWATER PATHWAY

		Yes (x)	Reference	Factor Value
1.	Is the depth to the aquifer of concern less than 800 feet?	×		5 (5)
2.	<ul> <li>(a) Within 2 miles of the site,         is the geologic material between the         vaste and the aquifer of concern         composed predominantly of sands, gravels         sandstone, limestone or dolomite?</li> <li>(b) Within 2 miles of the site,         is there evidence of a low hydraulic         conductivity layer (10<sup>-6</sup> to 10<sup>-9</sup>)between         the waste and the aquifer of concern?</li> </ul>	X		<u>5</u> (5)
3.	Only assign factor value for (a) or (b), choosing the higher value:  (a) is there a drinking water well(s) in the aquifer of concern or a more shallow unit of to 1/2 nile from the source(s)?		1,6	20 (20)
4.	(b) Is there a drinking water well(s) in the aquifer of concern or a more shallow un: 1/2 to 2 miles from the source(s)? Is the aquifer of concern a karst unit?		·	(5) (10)
5.	Is the aquifer of concern a sole source aquifer?	Mo		(5)
6.	Complete (a) and (b), and assign the <a href="https://documented.contamination.of-drinking-wells-with-TCL/TAL-compounds">https://documented.contamination.of-drinking-wells-with-TCL/TAL-compounds</a> , answer yeassign a factor value of 50.  (b) Calculate potential population and assign factor value as given below:		6	<u>O</u> (50)

Distance (mile)	Population	×	Distance Weighting Factor	-	Subtotal
0-1/4	224.5	×	0.25	=	56.13
1/4-1/2	350.3	×	0.16	=	56.05
1/2-1	2872.4	×	0.08	_	229.79
1-2	12203.6	×	0.05	-	610.18
2-3	10230.6	×	0.03	=	306.92
3-4	7549.8	×	0.02	=	151.00

Total  $[4/0.67] \times 1 = [4/1] (50=ax)$ 

#### SURFACE VATER PATEWAY

						Yes (x)	Reference	Factor Value
1.	Does site	lie within a n?	100-ye	ar or le	<b>ss</b>	. <u>No</u>		<u>O</u> (5)
2.		contamination drinking wate			o the	. <u>Ио</u> .		0 (20)
3.	Is this a	sole-source	urface	vates s	upply?	40		0 (10)
4.	of the si	ery (production to, or is a final state of the state of t	sbery	potentia	lly impac			<u>O</u> (5)
5.	the site	eation area co or is a recre within 15 mile	ation	area pot	entially		6	5 (5)
٤.	result of	itive environs the site, or ly impacted wi te?	16 4 6	.ensitive	envicon		6	<u>5</u> (5)
7.	7. Complete (a) and (b), and assign the higher factor value: (a) If there is documented contamination of a surface water intake with TCL compounds answer yes and assign a factor value of 50. (b) Calculate potential population and assign a factor value as given below:							
	Intake	Population	x .	• Pilut eighting		- Subt	total	

Intake	Population	=	* Dilution Weighting Factor	-	Subtotal
-61		2		-	
42		×.		•	
43	1	R		-	
		*		-	
		*		-	
		ż			

no intakes

		$\wedge$

TOTAL SURPACE WATER PATHWAY VALUE (100)

#### SURFACE WATER PATEWAY

# TABLE DILUTION WEIGHTING FACTORS

	Average Annual	
Surface .	Flow in Cubic .	Assigned
Characteristic	feet per Second (CFS)	<b>Value</b>
-		
Minimum perennial stream	Less then 5 cfs	2.5
Small to moderate stream	5 to 50 cfs	0.25
Koderate to large stream	Greater than 50 to 500 cfs	0.625
Large streams to rivers	Greater than 500 to 10,000 cfs	0.0013
Kajor rivers	Greater than 10,000 cfs	0.0003
Ocean or the Great Lakes	Not applicable	0.0003
Mixing zone of quiet flowing rivers	Greater than 50 cfs	0.125
Lakes, reservoirs	Add and average CFS of	Assign value
	tributaries flowing into	to calculated
	lake/sesesvois.	CFS figure
		using above
•		factors.

#### ON-SITE PATEWAY

			¥06	Reference	Factor Value
1.	Is the site located in an area where				
	people live or go to school within 1		\/	/	10
	mile of the source(s)?	•	$\Delta$	6	10 (10)
	"If answer 80 to Question 1, do not	•			
	proceed with the remaining questions.		. •		
2.	Is there known contemination from the				
	site on residential or school			•	-
	brober, A.		NO		<u></u>
3.	Is site public use land or		1	•	^
	widely used land without barriers?		NHM	`	(10)
4.	Complete (a), (b) and (c), and assign the				
	highest factor value:				
	Which of the following are adjacent to site/s	oatc	•(=)		
	or conteminated from the site?		. 10		$\sim$
	(a) Schools, day-care		<u>NO</u>		<u>(15)</u>
	(b) Parks, playgrounds, residences		<i>X</i>		<u>[D</u> (10)
	(c) National park, federal endangered				
	species, other public-use lands.				(51

5. Calculate population within 1 mile of the site, and assign factor value as given below:

Distance (mile)	Population		Distance Weighting Factor	-	Subtotal
0-1/4	224.5	2	0.05	-	11.23
1/4-1/2	350.3		0.025	-	8.78
1/2-1	2872.4	-	0.0125	-	35.91

Total 55.92 50 (Somer)

TOTAL OS-SITE PATEMAX VALUE 70 (100)

# APPENDIX

€.

Copies of the following addenda have been supplied to the U.S. Environmental Protection Agency and the appropriate state agencies. Refer to these addenda when reviewing this work plan.

Addendum	Title
<b>A</b>	Routine Analytical Services Contract Required Detection and Quantitation Limits
В	Central Regional Laboratory Detection Limits
C	Special Analytical Services Detection Limits Drinking Vater Samples
D	Special Analytical Services Detection Limits Bigh Concentration Samples

# **REFERENCES**

## REFERENCE DOCUMENTATION SHEET

Ref.#	DESCRIPTION OF REFERENCE
_	Illinois Department of Public Health, Well
	Construction Reports. Kane County Well
	Logs. (Selected logs T. 39N. R. BE, Secs.
	11, 13,15). 6 logs:
	Strand, Mr., July 20, 1988 telephone
	Conversation, Deputy Chief of the Batavia
٠.	City Fire Department, Batavia, Illinois
	(312)879-1404 contacted by Bill Schaefer
	Kreuger, Tim, July 22 telephone Conversation, IEPA, Springfield
	1L. (217) 782-0610, contacted by Bill Schoefer.
3	U.S. Environmental Protection Agency,
	Potential Hazardous Waste Site Preliminary.
	Assessment for Comerco Inc. Olympic
	Stain Div USEPA ID# 1LD085224186, prepared
·	by Kathy Freeman of the USEPA March 7, 1983.
4	U.S. Dept. of Commerce, Government Printing
	Office' 1963. Rainfall Frequency Atlas.
	Technical Paper No. 40, Washington, D.C., Pp. 43, 68.
*:	PP. 43, 68 ·

## REFERENCE DOCUMENTATION SHEET

Ret.¢	DESCRIPTION OF REFERENCE
5	Sax, I.N. 1984 Dangerous Properties
	of Industrial Materials, 6th ed.,
	New York, Van Nostrand Reinhold Company,
	Inc.
6.	U.S. G.S. Topographic Maps: 101964 Aurora
	North, @ Geneva, Illinois Quadrangles, 7.5
	Minute Series: 1:24000 (Both photorevised
	in 1972 and 1980)
-	
7	Endangered Species. U.S. Dept of the
	Interior. Fish and Wildlife Service.
8	Paul, Swaraj. Surface Coatings, Science and
	Technology, John Wley & Sons, NewYork, 1985.
*	

## REFERENCE DOCUMENTATION SHEET

(	
Re1.#	DESCRIPTION OF REFERENCE
9	RCRA Inspection Report - Interim Status
	Standards. Prepared by Brad Benning of
	the Illinois EPA, 12-81. EPA 10# 1LD085224186
	•
10	Woller, Dorothy and Sanderson, Ellis. Public
	Groundwater Supplies in Kane County. Bulletin
	60-22, Illinois State Water Survey, Urbana,
	Illinois, 1978.
-	
11	Illinois State File Information. This includes
	Notification of Hazardous Weste Site, NPDES application.
	and authorization.
	1
•	•
	·

## SOURCES AND DATES OF INFORMATION COLLECTION

SOURCE	DATE
1) State Hazardous/Solid Vaste Files 2) State Vater Files 3) State Air Files 4) State Department of Health 5) State Geological Survey 6) State Department of Natural Resources 7) State Fire Harshall 8) County Department of Health 9) County Engineer 10) County Clerk/Recorder of Deeds 11) City Department of Health 12) City Engineer 13) City Fire Department/Fire Marshall 14) City Vater/Sever Department	2-88 2-88, 7-22-88 2-88 2-88
15) U.S. Soil Conservation Service 16) Others  STATE CONTACT(S): Tom Crause  (name)  Kathy Freeman  (name)	(217) 782-9848 (phone number) (312) 886-6154 (phone number)